In-Flight Action Award David Fennen

Air Spray USA, Inc. employee, David Fennen, is the Pilot in Command of an Air Tractor AT-802AF, Fire Boss, on an exclusive use contract for the Alaska Fire Service.

On July 16, 2019, an in-flight incident occurred while working on the Lake Tsyooktuihvun fire. During the fourth scoop, the aircraft's fill scoops failed to retract causing the tank to fill to max capacity and subsequently overflowing out of the top, which reduced forward visibility out the windscreen to zero. Dave immediately activated the emergency dump system and jettisoned the load. As later determined during post-flight maintenance inspections, the scoops could not retract due to a mechanical issue. Therefore, during the scoop abort, the scoops continued to fill and visibility was not regained as would normally occur once they had retracted. Dave then selected max power and successfully accomplished a water takeoff. Once he was off the water surface and airborne again, visibility greatly improved. He then aborted the mission and returned to Fairbanks, without incident, for maintenance.

Dave is a well-respected pilot with years of experience in Alaska. He demonstrated outstanding airmanship and leadership and by doing so prevented damage to the aircraft and injury to personnel.

Thank you Dave for your positive actions during an in-flight incident!

Reference: SAFECOM 19-0351









Tracking #: 19-0351

Date Submitted: 7/17/2019 12:40:00 PM

EVENT

Date: 7/16/2019 Local Time: 1300 Injuries: No Damage: Yes

Location: Fire 572, Lake Tsyooktuihvun, State: Alaska

DOI Office of Aviation Services (DOI) > Bureau of Land Management (BLM) > Alaska State **Operational Control:**

Office > Alaska Fire Service

MISSION

Type: Fire, Retardant Drop (SEAT) Other: **Procurement:** Other: Exclusive use contract

Persons Onboard: Special Use: Yes Hazardous Materials: No

Departure Point: PAFB Destination: PAFB

AIRCRAFT

Manufacturer: Air Tractor Model: AT-802AF

NARRATIVE

During the fourth scoop the Fire Boss scoops failed to retract causing the tank to fill to max capacity subsequently blowing out the top which reduced forward visibility out the windscreen to zero. The PIC immediately activated the emergency dump system and jettisoned the load. As later determined during post-flight maintenance inspections, the scoops could not retract due to a mechanical issue. Therefore, during the scoop abort, visibility was not regained as would normally occur immediately after jettisoning the load once the scoops retracted. The PIC then selected max power and successfully accomplished a water takeoff. The PIC then aborted the mission and returned to Fairbanks for maintenance. BLM AV Safety, WS, 7/23: Scoops remained down after jettison of load and continued to fill causing visibility issues, after the water takeoff visibility improved out the windscreen. Excellent situational awareness by the pilot.

CORRECTIVE ACTION

Inspect scoops to determine cause of scoop retraction failure. BLM AV Safety, WS,7/23: The mechanical issue turned out to be a faulty hydraulic Vickers valve which was replaced by the mechanic. Operations checks were positive and OAS inspector returned the aircraft to contract availability on 7/18.

ATTACHMENTS

