

## **WARNING – Follow 4150 Transportation Instructions - WARNING**

1. Ensure battery terminals are covered during transportation.
2. If plastic terminal covers are missing cover terminals with tape to prevent shorts.
3. If spacer separating batteries is loose, secure batteries together with fiber tape to prevent movement and place the spacer to the side.
4. Do not transport if foam is damaged or missing.
5. Keep all foreign items out of the kit such as tools or stakes.

